# Strip Curtain Hanging Schemes

Showing how many 'pegs' to overlap each hanging plate by, and how many free pegs between each plate.

Hang the first row of strips with (the curvature of the material towards you), leaving the prescribed gap.
Hang the second row (curvature away from you) over the gaps.

200 wide strips

### Minimum Overlap

Medium Overlap

Maximum Overlap

Strip Curtain Hanging Schemes

Showing how many 'pegs' to overlap each hanging plate by, and how many free pegs between each plate.

Hang the first row of strips with (the curvature of the material towards you), leaving the prescribed gap.
Hang the second row (curvature away from you) over the gaps.

300 wide strips

Minimum Overlap

Medium Overlap

Maximum Overlap

Strip Curtain Hanging Schemes

Showing how many 'pegs' to overlap each hanging plate by, and how many free pegs between each plate.

Hang the first row of strips with (the curvature of the material towards you), leaving the prescribed gap.
Hang the second row (curvature away from you) over the gaps.

400 wide strips

Minimum Overlap

Medium Overlap

Maximum Overlap