



4 Professional Choices for Hygienic Wall and Ceiling Cladding

Datasheet 15 Cleaning Guidance

Cleaning the finished job

Where possible all off cuts from the job should be segregated for recycling Remove the protective surface film from the panels

Wipe down all surfaces with anti-static wipes

Any stubborn stains, silicon, or adhesive marks, can be cleaned with Proclad PVC cleaner.

Do not use any abrasive materials.

Cleaning in Service

Regular Cleaning

Wash with a solution of soap or detergent –always follow manufacturer's instructions

Never use any abrasive materials or liquids when cleaning Proclad – instead use soft cloths.

PVCu has a max temperature of 60 deg C – make sure that you do not exceed with during cleaning.

If the environment is dusty then all surfaces may be cleaned with antistatic wipes. Alternatively surfaces can be cleaned with an anti-static solution – again follow manufacturer's guidance.

Any stubborn stains, silicon, or adhesive marks, can be cleaned with Proclad PVC cleaner.

Panels can be safely washed with soapy water and hosed down.

In some environments it may be desirable to clean with a high pressure washer. In these cases never bring the lance any closer than 600mm to the wall surface and ensure that water temperature does not exceed 60 deg C

